

M Nut Size Chart

Nut Size (M)	Thread Diameter (mm)	Pitch (mm)	Across Flats (s)	Nut Height (m)
M3	3	0.5	5.5	2.4
M4	4	0.7	7	3.2
M5	5	0.8	8	4
M6	6	1.0	10	5
M8	8	1.25	13	6.5
M10	10	1.5	17	8
M12	12	1.75	19	10
M14	14	2.0	22	11
M16	16	2.0	24	13
M20	20	2.5	30	16
M24	24	3.0	36	19
M30	30	3.5	46	24